
#### SOUTH SIDE OF BRIDGE



#### ABUTMENTS ON NORTH SIDE OF BRIDGE



# EAST FLOOR BEAM



#### UNDERSIDE OF BRIDGE FACING EAST



# SPALL WITH EXPOSED REBAR CLIFF SWALLOW NESTS



#### VIEW LOOKING SOUTH EAST



#### GUARDRAIL ON NORTH SIDE OF BRIDGE



#### CONCRETE SIDEWALK ON NORTH SIDE




### SPALLING ON NORTH ARCH



#### VIEW SHOWING SOUTH ARCH



#### VIEW FACING EAST




#### VIEW FACING WEST




#### NORTH SIDE OF BRIDGE



#### VIEW LOOKING NORTH AT BEAR CREEK




#### VIEW LOOKING SOUTH AT BEAR CREEK



#### VIEW FACING WEST




# VIEW LOOKING EAST SHOWING BOWSTRING ARCH




#### DETAIL SHOWING CONCRETE PANELING



### FACING EAST



# FACING SOUTH



# SOUTH SIDE OF BRIDGE SHOWING UN-TEXTURED CONCRETE




#### NORTH SIDE OF BRIDGE



#### NORTH SIDE OF BRIDGE



#### VIEW FACING EAST



#### CONCRETE WEST ABUTMENT

